


PT(hybr)



MODEL	ØD	ØP	T	L	E	A	B	H (Hex)	ORIFICE	WEIGHT (g)	BOX(EA)
PT 1/4-01	1/4	13.0	R 1/8	27.0	20.5	8.0	16.8	12	4.0	16.4	50
PT 1/4-02			R 1/4	30.0		10.0		14		22.4	50
PT 1/4-03			R 3/8	31.0		11.0		17		42.4	50
PT 5/16-01	5/16	15.0	R 1/8	28.0	22.6	8.0	18.4	14	6.0	22.4	50
PT 5/16-02			R 1/4	31.0		10.0		14		26.4	50
PT 5/16-03			R 3/8	32.0		11.0		17		30.4	50
PT 3/8-01	3/8	17.5	R 1/8	28.5	23.8	8.0	20.1	17	6.0	34.4	25
PT 3/8-02			R 1/4	31.5		10.0		17		38.4	25
PT 3/8-03			R 3/8	32.5		11.0		17		43.4	25
PT 3/8-04			R 1/2	35.5		14.0		21		58.4	25
PT 1/2-02	1/2	21.0	R 1/4	35.0	28.3	10.0	23.1	19	9.0	45.0	25
PT 1/2-03			R 3/8	36.0		11.0		19		54.0	25
PT 1/2-04			R 1/2	39.0		14.0		21		74.0	20